

Work Order ID 61287

Friday, August 13, 2010 10:11:41 AM



Page 1

Item ID: D350-727-041

Accept



Setup Start



Revision ID:

Stop



Item Name: Wearplate, Standard, LH/RH

Start Date: 8/13/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 8/16/2010 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: MF

Date: 10-8-13

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
N/A	Rev N/A								

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D350-727-041 CHG001

MF

10-8-13

110

0.00



Pick Kit

Packaging

Memo

0.00

Packaging

120

0.00



QC4- 100% Inspect kits for completeness

QC

Memo

0.00

Quality Control

S. 10/8/13



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 61287

Friday, August 13, 2010 10:11:41 AM



Page 2

Item ID: D350-727-041

Accept



Setup Start



Revision ID:

Stop



Item Name: Wearplate, Standard, LH/RH

Start Date: 8/13/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 8/16/2010 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130

0.00



Packaging

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D350-727-041 □ Location: _____ □ PPP Rev: A

10/8/17 SP 20

140

0.00



QC21- Final Inspection - Work Order Release

QC

Memo

0.00

Quality Control

10/08/17 DJ
CX 10/8/17

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, August 13, 2010 10:11:40 AM

Page 1

Work Order ID: 61287

Parent Item: D350-727-041

Parent Item Name: Wearplate, Standard, LH/RH

Start Date: 8/13/2010



Required Date: 8/16/2010

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev: A005.05.12 New issue KJ/JLM



Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D3319-1		Manufactured	No			120	Each	11.0000	1	2			
													
Wearplate													

Location Loc Qty Loc Code

ST497 11
57710 11

+2

D3319-7		Manufactured	No			120	Each	10.0000	1	2			
													
Wearplate													

Location Loc Qty Loc Code

ST497 10
48545 10

+2

B57710 CY10/8/12

348545 CY10/8/12

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

32.3 WEIGHT AND BALANCE

There is negligible weight change associated with the installation of the Dart wearplates.

32.4 PARTS LIST

Qty -045	Qty -043	Qty -041	Qty -015	Qty -013	Qty -011	Part Number	Description
					X	D350-727-011	WEARPLATE KIT, STANDARD
				X		D350-727-013	WEARPLATE KIT, LONGER AFT WEARPLATE
			X			D350-727-015	WEARPLATE KIT, FULL LENGTH
		X				D350-727-041	WEARPLATE KIT, STANDARD WEARPLATE, LH/RH
	X					D350-727-043	WEARPLATE KIT, LONGER AFT, LH/RH
X						D350-727-045	WEARPLATE KIT, FULL LENGTH, LH/RH
1	1	1	2	2	2	D3319-1	WEARPLATE
1			2			D3319-3	WEARPLATE
	1			2		D3319-5	WEARPLATE
		1			2	D3319-7	WEARPLATE

• COPYRIGHT © 2005 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

32-00-00